

29 September 2020	
<b>Pengumuman MDKA – <i>Update</i> Insiden <i>Heap Leach Pad</i> di Operasi Tujuh Bukit</b>	<b>MDKA Announcement – Heap Leach Pad Incident at Tujuh Bukit Operations Update</b>
PT Merdeka Copper Gold Tbk (“ <b>MDKA</b> ” atau “ <b>Perseroan</b> ”) menyampaikan <i>update</i> atas insiden yang terjadi di proyek tambang Tujuh Bukit Perseroan yang berlokasi di Banyuwangi, Jawa Timur.	PT Merdeka Copper Gold Tbk (“ <b>MDKA</b> ” or “ <b>the Company</b> ”) provides an update on an incident that occurred at the Company’s Tujuh Bukit mining project located in Banyuwangi, East Java.
<u>Latar Belakang Insiden</u>	<u>Background to the Incident</u>
Sabtu 12 September 2020 pagi, ditemukan rekanan di permukaan pelataran pelindian atau <i>Heap Leach Pad</i> , sebagai tindakan, karyawan dan peralatan segera diamankan dari lokasi tersebut. Sabtu 12 September 2020, sore, terjadi pergeseran dari sebagian dari lereng hamparan bijih. Pergeseran materi tersebut menyebabkan kerusakan pada jalur perpipaan dan peralatan pompa. Namun, kejadian ini tidak menimbulkan korban cedera di kalangan karyawan ataupun memberikan dampak buruk bagi lingkungan.	On the morning of Saturday 12 September 2020, surface cracking was noted on the heap leach pad and employees and equipment were removed from the heap leach pad as a precautionary measure. In the afternoon of Saturday 12 September 2020 a portion of the ore that was stacked on the front face of the heap leach pad subsided. The movement of the material caused damage to some of the pipes and pumping equipment. Importantly the Company’s diligence ensured there were no injuries to personnel or environmental damage.
<u>Status Terkini</u>	<u>Current Status</u>
Operasi penambangan terbuka, pabrik persiapan bijih dan irigasi pada pelataran pelindian untuk sementara ditangguhkan sampai investigasi insiden dan pekerjaan remediasi selesai.	Open cut mining activities, operation of the ore preparation plant and irrigation of the heap leach pads has been suspended until the incident investigation and remediation works have been completed.
Diperkirakan rancangan pekerjaan remediasi akan siap pertengahan Oktober. Pergeseran muka tanah terus dipantau dengan prisma yang mengukur pergerakan. Pengukuran menunjukkan bahwa pergeseran muka tanah mulai stabil sehingga memungkinkan pekerjaan remediasi.	We expect the design of the remediation works to be finalised by mid October. The subsidence is being monitored with prisms that measure movement. These measurements indicate that the subsidence is stabilising which is a critical first step in allowing remediation work to begin.
Pengurasan cairan dari <i>heap leach pad</i> dikumpulkan di kolam air proses. Cairan kemudian diproses melalui pabrik ADR dan sirkuit detoksifikasi yang menghasilkan tingkat produksi emas yang lebih rendah. Hal ini diperkirakan akan berlanjut selama kuartal	Solution draining from the heap leach pad is being collected in the process water ponds. The solution is then being processed through the ADR plant and detoxification circuit leading to low levels of gold production. This is expected to continue during the fourth quarter. The Company does not

keempat. Perseroan tidak mengantisipasi dampak lingkungan buruk dari kejadian ini.	anticipate any adverse environmental impact from this incident.
Pompa dan infrastruktur lainnya telah diselamatkan dan dapat digunakan untuk kembali beroperasi.	Pumps and other infrastructure have been recovered and will be available to restart operations.
<u>Perkiraan Produksi Emas</u>	<u>Gold Production Forecast</u>
Perseroan bekerja sama dengan banyak ahli dalam perancangan pelataran pelindian ( <i>heap leach design</i> ) untuk menentukan penyebab insiden agar tidak terulang kembali di masa mendatang. Saat ini, irigasi pelataran pelindian tidak akan dilakukan pada kuartal ke-empat. Produksi akan berasal dari pemrosesan larutan yang diambil dari pelataran pelindian. Penjualan sekitar 10.000 ounce diharapkan untuk kuartal ke-empat. Total produksi tahun ini diperkirakan 154.000 sampai 160.000 ounce.	The Company is working with numerous experts in heap leach design to determine the cause of the incident to prevent it re-occurring in the future. At this stage no irrigation of pads is expected to occur in the fourth quarter. Production will come from processing of solutions drawn down from the heap leach pads. Sales of approximately 10,000 ounces are expected to occur in the fourth quarter. Total production for the year is expected to be 154,000 to 160,000 ounces.
Perencanaan perbaikan bertujuan untuk memulai kembali produksi secara berkelanjutan. Diperkirakan sekitar sepertiga dari <i>heap leach pad</i> tidak terpengaruh oleh pergeseran permukaan tanah. Setelah ini dipastikan dan pemompaan dan pemipaian tambahan telah terpasang kembali (menggunakan pompa yang dipulihkan), Perseroan memperkirakan bahwa irigasi pelataran dapat dimulai kembali pada Januari 2021.	The remediation plan is focused on how to sustainably restart production. Approximately one third of the heap leach pad is believed to be unaffected by the subsidence. Once this is confirmed and additional pumping and piping has been installed (using the recovered pumps), the Company anticipates that irrigation of the heaps may recommence in January 2021.
<u>Dampak Keuangan</u>	<u>Financial Impact</u>
Pada 30 September 2020, Perseroan akan memiliki cadangan kas sekitar US\$ 80 juta setelah pembayaran amortisasi hutang terjadwal sebesar US\$ 10 juta. Perseroan mengantisipasi bahwa akan memiliki pendanaan yang cukup untuk melanjutkan investasi di Proyek Tembaga Tujuh Bukit dan studi kelayakan AIM.	As of 30 September 2020 the Company will have cash reserves of approximately US\$ 80 million after payment of scheduled debt amortisation of US\$ 10 million. The Company anticipates that sufficient funding will be available to continue with investments in the Tujuh Bukit Copper Project and AIM feasibility studies.
Perseroan memiliki polis asuransi yang komprehensif termasuk untuk kerusakan material dan gangguan usaha. Penanggung asuransi telah diberitahu tentang kejadian tersebut dan penilai kerugian telah ditunjuk oleh perusahaan asuransi. Kunjungan penilai	The Company has comprehensive insurance policies including material damage and business interruption. Insurers have been advised of the incident and a loss adjuster has been appointed by insurers. A site visit by the loss adjusters has been completed and the Company is providing

kerugian telah dilaksanakan dan Perseroan menyediakan informasi agar klaim dapat dinilai. Proses ini diperkirakan akan membutuhkan waktu hingga dua bulan.	information to enable the claim to be assessed. This process is expected to take up to two months.
<u>Cadangan Bijih</u>	<u>Ore Reserves</u>
Penting untuk dicatat bahwa diperkirakan bahwa tidak ada emas hilang dari cadangan. Produksi akan ditangguhkan karena insiden ini. Perseroan juga sedang mengupayakan untuk meningkatkan potensi cadangan bijih di situs melalui eksplorasi dan pengoptimalan ulang desain lubang tambang untuk menarik keuntungan dari harga emas yang lebih tinggi saat ini.	It is important to note that no gold is expected to be lost from reserves. Production will be deferred due to this incident. The Company is also working on the potential to expand the ore reserves at the site through exploration and re-optimisation of the pit designs to reflect the recent higher gold price.
Pengumuman lebih lanjut akan dilakukan segera setelah pekerjaan desain remediasi selesai dan perkiraan produksi rinci telah disiapkan.	A further announcement will be made as soon as the remediation design works are complete and a detailed production forecast has been prepared.
<b>Kontak Informasi/For further information please contact:</b>	
Untuk informasi umum/General Information: Tom Malik Corporate Communication E: <a href="mailto:tom.malik@merdekacoppergold.com">tom.malik@merdekacoppergold.com</a>	Untuk hubungan investor/Investor Relations: Mirdal Vismara Timoer Investor Relations E: <a href="mailto:investor.relations@merdekacoppergold.com">investor.relations@merdekacoppergold.com</a>
<b>Tentang PT Merdeka Copper Gold Tbk.</b>	<b>About PT Merdeka Copper Gold Tbk.</b>
PT Merdeka Copper Gold Tbk (“MDKA” atau “Perseroan”) adalah perusahaan induk dengan anak-anak perusahaan yang beroperasi di dalam kegiatan-kegiatan usaha pertambangan, meliputi (i) eksplorasi dan (ii) produksi emas, perak, tembaga (dan mineral terkait lainnya), dan (iii) jasa pertambangan	PT Merdeka Copper Gold Tbk (“MDKA” or “the Company”), a holding company with operating subsidiaries engaging in mining business activities, encompassing: (i) exploration; (ii) production of gold, silver, copper (and other related minerals); and (iii) mining services.
Perseroan saat ini terdiri atas lima aset/proyek utama, yaitu (i) Proyek Tembaga Tujuh Bukit, (ii) Pani Joint Venture, (iii) Proyek Wetar/Morowali Acid Iron Metal, (iv) Tambang Emas Tujuh Bukit dan (v) Tambang Tembaga Wetar.	The Company’s current major assets are the: (i) Tujuh Bukit Copper Project; (ii) Pani Joint Venture; (iii) Wetar/Morowali Acid Iron Metal Project; (iv) Tujuh Bukit Gold Mine and; (v) Wetar Copper Mine.